

PHOTO 10 KIYU CREEK, SOUTH CHANNEL, LOOKING UPSTREAM




PHOTO 2. KIYU CREEK. LOOKING DOWNSTREAM AT THE CHANNEL SPLIT

HAY & COMPANY CONSULTANTS INC.

MINISTRY OF PARKS
NIMPKISH RIVER
ECOLOGICAL RESERVE

PHOTOGRAPHS 1 AND 2





SH AT NORTH END OF ISLAND

PHOTOGRAPHS 3 AND 4




PHOTO 5: ERODING BANK. WEST SIDE OF ISLAND



PHOTO 6: LOOKING UPSTREAM ALONG WEST SIDE OF ISLAND, NOTE LOG DEBRIS HAY & COMPANY CONSULTANTS INC.

MINISTRY OF PARKS

NIMPKISH RIVER ECOLOGICAL RESERVE PHOTOGRAPHS 5 AND 6



PHOTO 7. NIMPKISH RIVER. LOOKING DOWNSTREAM ALONG 1987 BERM



PHOTO 8: MAIN CUTOFF CHANNEL. LOOKING SOUTH ACROSS RIPRAP AND 1987 BERN

HAY & COMPANY CONSULTANTS INC.

MINISTRY OF PARKS
NIMPKISH RIVER
ECOLOGICAL RESERVE

PHOTOGRAPHS 7 AND 8